


0031




Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (801) 888-4476 • Fax (801) 888-2538

Nov. 24, 1999

Department of Environmental Quality
Division of Water quality
288 North 1460 West
P.O. Box 144870
Salt Lake City, Utah 84114-4870



Attention: Mr. Michael Herkimer

ACT/607/035 #7

Subject: November 1999, UPDES Compliance Report
October 1999, Monitoring Period
UPDES Permit No. UT0024759
Discharge Monitoring Report Forms
Sunnyside Cogeneration Facility, Sunnyside, Utah

— Ken
— Mike

Then to binders

Dear Mr. Herkimer:

This letter summarizes the UPDES-Permit field activities at the Sunnyside Cogeneration Facility during October 1999. Rusty Netz, the Environmental Coordinator for the facility, has physically inspected the permit outfalls in accordance with the UPDES permit guidelines.

There were no discharges during the October 1999, monitoring period. The completed Discharge Monitoring Report Forms (EPA No. 3320-1) are included in Attachment A. The Field Data Sheets are included in Attachment B.

If you have any questions concerning this report, please contact me at (435) 888-4476.

Sincerely,

Rusty Netz

Rusty Netz
Environmental Coordinator

RN/ta
Enclosures:

Attachment A: Monitoring Report Forms
Attachment B: Field Data Sheets

cc: Ken Wyatt, Division of Oil, Gas and Mining
SCA Plant file
Rusty Netz, COSI